

2 Specification

▶ First group of parameters: Alarm setting value

Symbol	Name	Content	Address	Range
AV	Av	Comparison value of deviation alarm mode	00H	-1999~9999
AH	AH	1st alarm point setting value	01H	-1999~9999
AL	AL	2nd alarm point setting value	02H	-1999~9999
AHH	AHH	3rd alarm point setting value	03H	-1999~9999
ALL	ALL	4th alarm point setting value	04H	-1999~9999

▶ Second group of parameters: alarm configuration

Symbol	Name	Content	Address	Range
oA	oA	Passcode	10H	0~9999
ALo1	ALo1	1st alarm point alarm mode	11H	Note1
ALo2	ALo2	2nd alarm point alarm mode	12H	Note1
ALo3	ALo3	3rd alarm point alarm mode	13H	Note1
ALo4	ALo4	4th alarm point alarm mode	14H	Note1
HYA1	HYA1	1st alarm point sensitivity	19H	0~8000
HYA2	HYA2	2nd alarm point sensitivity	1AH	0~8000
HYA3	HYA3	3rd alarm point sensitivity	1BH	0~8000
HYA4	HYA4	4th alarm point sensitivity	1CH	0~8000
cYt	cYt	Alarm delay	1FH	0 ~ 20

▶ Third group of parameters: Polyline operation

Symbol	Name	Content	Address	Range
c1	c1	1st polyline point measurement	20H	-1999~9999
b1	b1	1st polyline point standard value	21H	-1999~9999
c2	c2	2nd polyline point measurement	22H	-1999~9999
b2	b2	2nd polyline point standard value	23H	-1999~9999
c3	c3	3rd polyline point measurement	24H	-1999~9999
b3	b3	3rd polyline point standard value	25H	-1999~9999
c4	c4	4th polyline point measurement	26H	-1999~9999
b4	b4	4th polyline point standard value	27H	-1999~9999
c5	c5	5th polyline point measurement	28H	-1999~9999
b5	b5	5th polyline point standard value	29H	-1999~9999
c6	c6	6th polyline point measurement	2AH	-1999~9999
b6	b6	6th polyline point standard value	2BH	-1999~9999
c7	c7	7th polyline point measurement	2CH	-1999~9999
b7	b7	7th polyline point standard value	2DH	-1999~9999
c8	c8	8th polyline point measurement	2EH	-1999~9999
b8	b8	8th polyline point standard value	2FH	-1999~9999

▶ Fourth group of parameters: Measurement and display

Symbol	Name	Content	Address	Range
incH	incH	Input signal selection	30H	0 ~ 7
in-d	in-d	Show decimal point position selection	31H	Note2
u-r	u-r	Lower limit of measuring range	32H	-1999~9999
F-r	F-r	Upper limit of measuring range	33H	-1999~9999
in-A	in-A	Zero point correction value	34H	-1999~9999
Fi	Fi	Full scale correction value	35H	0.500~1.500
FLtr	FLtr	Digital filter time constant	36H	1 ~ 20
c-b	c-b	Polyline function selection	37H	Note3
Zror	Zror	Clear range	38H	0 ~ 9999
Zrot	Zrot	Key clear effective time	39H	0 ~ 6
At	At	Display update rate	3AH	1~60
bout	bout	Failure proxy value	3CH	-1999~9999
HL	HL	Setting value display selection	3DH	0~6
Fbc	Fbc	Operating mode	3EH	Note3
Fbao	Fbao	Window 1 shows selection	3FH	0 ~ 3

▶ Fifth group of parameters: Communication interface, transmission output, etc.

Symbol	Name	Content	Address	Range
Add	Add	Communication address	40H	0 ~ 99
bAud	bAud	Communication speed selection	41H	Note4
ctd	ctd	Alarm output control right selection	44H	Note 3
ctA	ctA	Transmission output controight selection	45H	Note 3
oA1	oA1	Alarm setting password selection	46H	Note3
oP	oP	Output signal selection	4DH	0 ~ 2
bA-L	bA-L	Transmission output lower limit	4EH	-1999~9999
bA-H	bA-H	Transmission output upper limit	4FH	-1999~9999

Note1: 0 ~ 4

--- H to --- P⁵ alarm methods

Note2: 0 ~ 3

0000, 0000, 0000, 0000.

Note3: 0 OFF, 1 ON.

Note4: 0 ~ 3 2400, 4800, 9600, 19.2k

3 Parameter setting method

The parameters of the instrument are divided into several groups, and the group of each parameter is listed in the "Parameter List".

★ Parameters in Group 2 and later are controlled by password and cannot be entered without setting a password.

★ Whether the first group of parameters is controlled by password can be selected by setting parameter oA1. When set to OFF, it is not controlled by password; when set to ON, if no password is set, although you can enter and modify, you cannot save.

★ After entering the setting state, if no key operation is performed for more than 1 minute, the instrument will automatically exit the setting state.

3.1 How to set the alarm set value

The alarm setting value is in the first group of parameters. Instruments without alarm function do not have this group of parameters.

- Press and hold the setting key for more than 2 seconds without releasing it to enter the setting state, and the instrument displays the symbol of the first parameter.
 - Press key to select other parameters of this group in sequence.
 - Press the key to call up the original setting value of the current parameter, and the flashing bit is the correction bit.
 - Use the key to move the modification bit, the key to increase the value, and the key to decrease the value, and modify the parameters to the required values.
 - Press the key to save the modified parameters and go to the next parameter. If it is the last parameter of this group, pressing the key will exit the setting state.
- Repeat steps ② ~ ⑤ to set other parameters of this group.

3.2 Password setting method

When the instrument is in the measuring state or the first group of parameter symbols are displayed, the password can be set.

- Press and hold the setting key until is displayed.
- Press the key to enter the modification state, and modify it to 1111 with the cooperation of the , , and keys.
- Press the key to complete the password setting.

★ The password will be automatically cleared when the instrument is powered on or if there is no key operation for more than 1 minute.

3.3 How to set other parameters

- First set the password according to the password setting method.
 - Because the second group of parameters is the group where the password parameters are located, after the password setting is completed, press the key to select each parameter of this group.
 - The parameters of other groups, by holding down the set key , enter each parameter group in sequence, and the meter displays the symbol of the first valid parameter of the group.
 - After entering the group where the parameters that need to be set are located, press the key to cycle through the parameters that need to be set in this group.
 - Press the key to call up the original setting value of the current parameter, and the flashing bit is the modification bit.
 - Use the key to move the modification bits, the key to increase the value, and the key to decrease the value, and modify the parameters to the required values.
 - Press the key to save the modified parameters and go to the next parameter.
- Repeat steps ④ ~ ⑦ to set other parameters of this group. Exit setting: When the parameter symbol is displayed, press and hold the setting key until you exit the parameter setting state.

★ For parameters that represent parameter values in symbolic form, when modified, the flashing bit should be in the last position.

Function corresponding parameter description

1 Measurement and display

The process of the instrument from sampling to display:

Sampling → Digital filtering → Dimension conversion → Adjustment → Line operation → Reset → Peak and valley value detection → Display

8] aYb] cb` Wb] Yf] cb. `j` c` hU] Yz` WffYbzh` aJ` g] [bU` UWWfX] b] `hc` hY` gYh` fUb] Y` cZ` the upper and lower limits of conversion.
 =b` g` dYWU` WgYz` hY` g] [bU` df` c]] XYX Vm hY` i` gYf` Wb` U` g` c` WY` WadLFYX` k] h\` hY` X] g` d` UnYX` hUV` Y` cf` Zcf` ai` U`
 5X` i` ghaYbh` `GY` hY` 5X` i` ghaYbh`] bghfi` W] cbg`
 Pc` m] bY` cdYf` Uh] cb. `GY` hY` X] gW] dh] cb` cZ` , !` gYW] cb] dc` m] bY` cdYf` Uh] cb` Zi` bW] cb`
 HY` dUf` UaYhYf` g` Zcf` aYUgi` f` YaYbh` Ux` X] g` d` Un` UY` `] ghYX` WY` ck` `=bWff` YW] G` Yh] b] g` aUn` W] gY` hY` aYhYf` `hc` X] g` d` Un` Ubcf` aU` `m`
 HY` X] g` d` Un] g` U` g` c` UZZY` W] X` Vm` h] b] b] `Ux` dc` m] bY` cdYf` Uh] cbg`

▶ (incH) — `=bdi` h` g] [bU` `gY` YW] cb

HY` gYh] b] g` c] ` X` W` Wb] gYh] k] h\` hY`] bghfi` aYbh` acXY` Ux` hY` Umi` U` `] bdi` h` g] [bU` ` `HY`] U` iY` cZ` h] g` dUf` UaYhYf` `] g` fYdY` gYhYX] b` gnaVc`] WZcfaz` Ux` hY` WffY` gdc` b] b] fY` Uh] cbg] dg` UY` `] ghYX] b] hY` Zc` `ck] b] `hUV` Y.

0	4-20	4mA~20mA
1	0-10	0mA~10mA
2	0-20	0mA~20mA
3	1-5u	1V~5V
4	0-5u	0V~5V
5	20mV	±20mV
6	50mV	±50mV
7	90mV	±90mV

- ▶ (in-d) — `LcW] bh] gY` YW] cb` cZ` hY` XW] aU` `dc] bh` X] g` d` UnYX`
- ▶ (u-r) — `Lower range limit
- ▶ (F-r) — `Upper range limit

These two parameters specify the start and end of the display value corresponding to the start and end of the input signal.

- ▶ **FLTr** (FLTr) — Digital filtering time constant

Used to overcome the display fluctuation caused by signal instability, the larger the set value, the stronger the effect, but the slower the change of the input number. This parameter is factory set to 1.

- ▶ **At** (At) -- Shows the update rate

The sampling rate of the meter is 10 times per second. The value set in the **At** parameter indicates the number of samples required to perform an average calculation for displaying one update. For example, if **At** is set to 5, the system displays the update once after the average of the five samples.

The cycle of alarm and transmission output is 10 times/second, which has nothing to do with this parameter.

- ▶ **HL** (HL) -- The second window shows the selection

The instrument with a setpoint display displays a setpoint through the selection of this parameter. The value ranges from 0 to 6, corresponding to xxx, xxx, xxx, xxx, peak value, and valley value.

2 Reset

- ▶ **Zror** (Zror) -- Clear zero range, factory set to 0
- ▶ **Zrot** (Zrot) - Key clear valid time

The setting range is 0-6 seconds. When it is set to 0, the measured value is within the zero clearing range, and you can clear it by pressing the button. In the measuring state, when the measured value is within the zero clearing range, there are three ways to achieve the zero clearing of the measured value:

- ① Press the **▼** key for a certain amount of time (set by **Zrot**) to clear the measured value to zero.
- ② The external opening "Clear zero" is closed for a certain time (set by **Zrot**), and the measured value is cleared to zero.
- ③ Clearing by the host computer through the communication interface.

3 Peak and valley value detection

- ▶ **Fbc** (Fbc) -- Work mode selection

When set to **OFF**, work in normal mode, only the measured value;

When the value is set to **ON**, the meter performs peak and valley value detection while working in peak and valley mode.

- ▶ **FbRo** (Fbc) -- Display selection

When set to 0: The first window displays the measured value;

- 1: Press the MOD key to display the measured value and peak value in the first window;
- 2: Press the MOD key to display the measured value and valley value in the first window;
- 3: Press the MOD key to display the measured value, peak value and valley value in the first window;

When the instrument works in peak-valley mode, the peak-valley value is judged for each measurement and control period. Press the MOD key to switch the first window to display the measured value, peak value, and valley value. When the peak and valley value are displayed, the last decimal point of the first window is lit.

In the measurement state, **Fbc = ON**, there are two ways to clear the peak and valley values:

- ① Press **◀** to clear the peak and valley values;
- ② The upper computer clears the peak and valley values through the communication interface;

Note: If **Fbc = OFF**, the **FbRo** parameter is invalid, and **HL** should be set to 0 to 4.

4 8 section line operation function

This function is an optional function.

When the input signal and display data show monotonically increasing nonlinearity, and the data cannot be determined when ordering, and need to be corrected during calibration, the instrument's polyline calculation function can be used.

Monotonically rising means that within the full range of the input signal, as the input signal increases, the displayed data also increases.

- ① Relevant parameters of polyline operation:


- ▶ **c-b** (c-b) — Polyline function selection
- ▶ **c1 ~ c8**: Indicates the measurement value of each polyline point
- ▶ **b1 ~ b8**: Indicates the standard value of each polyline point

Measured value: refers to the displayed value before the polyline operation. Standard value: refers to the expected display value after the polygonal operation.

- ② Instructions

- The polyline operation is performed after dimension conversion and adjustment, and relevant parameters should be set according to "Adjustment".
- Select the **c-b** parameter as OFF to turn off the polyline operation function.
- After the instrument is connected to the input signal, increase the input signal from small to large. During this process, record the measured values and standard values of each breakline point, that is, **c1 ~ c8**, **b1 ~ b8** are obtained.
- Select the **c-b** parameter to ON, turn on the polyline operation function, and set the **c1 ~ c8**, **b1 ~ b8** parameters.

- ③ Schematic diagram



★ If the measured value is less than C1, the instrument will push downward according to the data in the next section;

★ If the measured value is greater than C8, the instrument will push upward according to the data of the previous section;

5 Alarm output

This function is an optional function.

The instrument can be configured with up to 4 alarm points. Each alarm point has 3 parameters, which are used to set the alarm value, select the alarm mode and set the alarm sensitivity.

- ▶ **RH, RL, RHH, RLL** The sequence is the alarm setting values of the 1st to 4th alarm points.

- ▶ **AL01 ~ AL04** The sequence is the alarm mode selection of 4 alarm points.

- ▶ **HYA1 ~ HYA4** The sequence is the alarm sensitivity setting of 4 alarm points.

There are also 2 common parameters for alarm output:

- ▶ **Av** (Av) — Comparison value of deviation alarm mode

An alarm occurs when the deviation between the measured value and this value exceeds the set value. The non-deviation alarm mode has nothing to do with this parameter.

- ▶ **cYt** (cYt) — Alarm delay

The setting range is 0-20 seconds. When it is 0, there is no alarm delay function.

When the measured value exceeds the alarm set value, the alarm delay is started. If the measured value is always in the alarm state during the alarm delay period, the alarm signal will be output at the end of the alarm delay. Otherwise, no alarm signal will be output.

Alarm recovery is also controlled by a delay.

- ▶ Alarm mode: There are 5 alarm modes. Select the alarm mode of each alarm point through **AL01 ~ AL04** parameters.

- Select as
- - - **H**: Upper limit alarm, alarm when measured value > set value.
 - - - **L**: Lower limit alarm, alarm when measured value < set value.
 - **PAH**: Deviation upper limit alarm, (measured value - **RU**) > set value alarm.
 - **PAL**: Lower limit of deviation alarm, (**RU** - measured value) > set value alarm.
 - - **PA**: Deviation absolute value alarm, (**RU** - measured value) > set value alarm.

- ① In the deviation alarm mode, the alarm setting value cannot be a negative number.

- ▶ Alarm sensitivity: In order to prevent the alarm relay from frequently operating when the measured value fluctuates near the alarm set value, an extended area for alarm release can be set as needed.

- ① For instruments with communication functions, when the **ctd** parameter is selected as ON, the instrument will not perform alarm processing.

6 Transmission output

This function is an optional function. The transmission output has 3 parameters:

- ▶ **OP** (op) — Output signal selection

- Select as
- 4-20**: Output is 4mA -20mA (or 1 V -5V)
 - 0-10**: Output is 0mA -10mA
 - 0-20**: Output is 0mA -20mA (or 0 V -5V, or 0 V -10V)

- ▶ **ba-L** (ba-L) — Transmission output lower limit setting

- ▶ **ba-H** (ba-H) — Transmission output upper limit setting

- ① For instruments with communication functions, when the **ctA** parameter is selected as ON, the instrument does not perform transmission output processing.

7 Communication interface

This function is an optional function. There are 4 parameters related to the communication function:

- ▶ **Add** (Add) — Instrument communication address. Setting range 0-99. Factory setting is 1.

- ▶ **bAud** (bAud) — communication rate selection. There are 4 types available: 2400, 4800, 9600, and 19.20k. The factory setting is 9600.

- ▶ **ctd** (ctd) — Alarm output right selection. Factory setting is OFF. When ON is selected, the instrument is controlled by the alarm function. When OFF is selected, control is transferred to the computer, and the alarm output is directly controlled by the switch output command issued by the computer.

- ▶ **ctA** (ctA) — Transmission output control right selection. Factory setting is OFF.

When OFF is selected, the instrument outputs according to the transmission output function. When ON is selected, control is transferred to the computer, and the transmission output is directly controlled by the analog output command issued by the computer.

For details of the relevant communication commands and protocols, see "Communication Protocol". The commands related to the instrument are as follows:

- #AA✓ Read measured values
- #AA01✓ Read peak value
- #AA02✓ Read valley
- #AA2222✓ Clear measured value
- #AA3333✓ Clear peak and valley value
- #AA0001✓ Read the output analog value (transmission output)
- #AA0002✓ Read switch input status
- #AA0003✓ Read switch output status (alarm output)

- ' AABB✓ Expression symbol (name) for reading instrument parameters
- \$AABB✓ Read instrument parameter values
- %AABB(data) ✓ Set instrument parameters
- &AA(data) ✓ Output switching value
- &AABBDD✓ Output analog value

■ Adjustment

During adjustment, zero point correction should be performed first, and then full scale correction should be performed.

- ▶ Z_{n-R} (in-A)——Zero point correction value. The factory setting is generally 0.
- ▶ $F_{\bar{c}}$ (Fi)——full scale correction value. The factory setting is generally 1.000.
Display value = (Display value before zero point correction + Z_{n-R}) × $F_{\bar{c}}$

■ Input fault signal processing

Using the input signal fault processing function of the instrument can more effectively ensure the safe operation of the equipment and abnormal equipment operation caused by input signal faults, such as interlocking, shutdown, etc. The meter displays $\square \downarrow$ indicating input signal failure. Parameter settings can still be made when the instrument displays $\square \downarrow$.

Input signal failure is caused by overflow of the A/D conversion in the instrument due to excessive input signal.

- ▶ b_{out} (bout)——surrogate measurement value when input signal fails

When the instrument determines that the input signal is faulty, the set b_{out} value is used as the input value of the alarm output and transmission output. The input signal fault alarm output function can be added according to user requirements.

❗ If the instrument does not have alarm output function, transmission output function and communication function, this parameter will have no effect.

■ Specification

1 Basic specifications

Supply voltage	AC power	100-240 V AC 50/60 Hz
	AC/DC power	10-24V AC 50/60 Hz; 10-24V DC
Power consumption	AC power	Below 7 VA
	AC/DC power	AC: Below 6 VA ; DC: Below 5W
Allowable voltage variation range	90 ~ 110% of power supply voltage	
Insulation resistance	100MΩ or more (500 V DC MEGA reference)	
Withstand voltage	1 minute at 2000 V AC 50/60Hz	
Anti-interference	IEC61000-4-2 (electrostatic discharge), level III; IEC61000-4-4 (electrical fast transient burst), level III; IEC61000-4-5 (surge), level III	
Protection level	IP65(Product front part)	
Environment	Temperature	-10 ~ 55°C; storage -25 ~ 65°C
	Humidity	35 ~ 85 %RH; storage 35 ~ 85 %RH

2 Input specifications

Measure control speed	10 times/second or more		
Basic error	±0.2 %F.S		
Display range	-1999~ 9999		
Input signal	Voltage	V	0-5V DC; 1-5V DC
	Current	I	4-20/0-10/0-20 mA
	mV	M	±20, ±50, ±90 mV
Digital filtering	Inertia; average; moving average, etc.		

3 Optional accessories specifications

Contact output	A1-A4	1-4 points, 250VAC/3A resistive load	
Contact input	K	1 external binary input for clearing	
Analog output (resolution on 1/3000)	M1	Current output (4-20)mA, (0-10) mA, (0-20) mA	
	M2	Voltage output (1-5) V, (0-5) V	
Communication interface	C1	TC ASCII protocol RS232	Rate: 2400; 4800; 9600; 19200 TC Address: 0~99 Response time: 500μS (measured value)
	C2	ASCII protocol RS485	
	R1	Modbus-RTU protocol RS232	
	R2	Modbus-RTU protocol RS485	
External power supply	P1	24V±5%, below 50mA	
	P1G	24V±5%, below 100mA	
	P2	12V±5%, below 50mA	
	P2G	12V±5%, below 100mA	
	P3	Precision power supply, generally 10V±2%, 30ppm, below 100mA	

■ Contact Us

ATO

Phone: +1800-585-1519

E-mail: sales@ato.com

Website: www.ato.com