



V2.8

FULL TEMPERATURE COMPENSATION INCLINOMETER HCA716/HCA726

Technical Manual











o Revision date: 2025-5-27

Note: Product functions, parameters, appearance, etc. will be adjusted as the technology upgrades, please contact our pre-sales business to confirm when purchasing.

Disclaimer

This product is developed exclusively for commercial applications and is prohibited from being used for illegal purposes, such as military activities, research related to nuclear, chemical, or biological weapons, or any other actions that violate laws and regulations. It is strictly forbidden to engage in activities related to goods embargoed by the United Nations, the European Union, or the OSCE, as well as any other activities prohibited by the Export Administration Regulations.

Without the written consent of our company, this product must not be transferred to any third party. Purchasing this product signifies your acceptance of this disclaimer and your agreement to sign the related liability agreement. If these regulations are violated, all responsibilities will be borne by the purchaser, and our company will not be held liable.











▶ GENERAL DESCRIPTION

HCA716S/HCA726S is a small volume full temperature compensated high-precision single / dual-axis inclinometer for industrial field control. It adopts RS485 / RS232 serial access interface. Built-in high-precision 24bit A / D differential converter, through the 5th order filtering algorithm, can measure the tilt and pitch angle of the sensor output relative to the horizontal plane. The product integrates the latest technology main MEMS tilting unit, the measure range up to ±180°, and the full-scale accuracy is 0.01°, which can easily achieve dual-axis and single-axis tilt measurement. The product belongs to a real industrial grade product, with reliable and stable performance, good scalability, and multiple output options. It is suitable for the application of monitoring of ancient buildings, dilapidated buildings, ancient walls, etc., and large-scale high-precision measurement in industrial sites.


▶ FEATURES

- ★ Single / dual axis inclination measurement
- ★ Accuracy: Refer to data table
- ★ Wide temperature operation -40 ~ + 85 °C
- ★ IP67 protection grade
- ★ Direct lead interface

- ★ Range ±1 ~ ±180 ° optional
- ★ DC 9 ~ 36V wide voltage input
- ★ Resolution 0.001 °
- ★ High vibration resistance> 100g

▶ APPLICATION

- ★ Monitoring of ancient buildings and dilapidated buildings
- ★ Leveling of construction vehicles
- ★ Medical equipment angle control
- ★ Underground drilling rig attitude navigation
- ★ Monitoring of bridges and large lands
- ★ Mining machinery, oil drilling equipment
- ★ Railway gauge ruler and gauge leveling
- ★ Geological equipment tilt monitoring
- ★ Elevation angle measurement of directional satellite communication antenna











▶ SPECIFICATIONS

| HCA716/H | CA726 | CONDITION PARAMETERS | | | | | | UNIT | |
|---------------|----------------|---|---|--------------|--------------|---------------|------------|---------|--|
| Measure range | | | ±10 | ±30 | ±60 | ±90 | ±180 | ٥ | |
| Measure a | xis | | ΧY | ΧY | ΧY | ΧY | X | axis | |
| Resolution | | | 0.001 | 0.001 | 0.001 | 0.001 | 0.001 | ٥ | |
| Measure | MAXE | Room temp. | 0.008 | 0.01 | 0.01 | 0.02 | 0.02 | 0 | |
| accuracy | RMSE | Room temp. | 0.004 | 0.005 | 0.005 | 0.006 | 0.006 | ٥ | |
| Zero Temp | .coefficient | -40 ~ 85℃ | ±0.0005 | ±0.0005 | ±0.0005 | ±0.0005 | ±0.0005 | °/°C | |
| Sensitivity | temp coeffi | -40 ~ 85℃ | ≤0.01 | ≤0.01 | ≤0.01 | ≤0.01 | ≤0.01 | %/°C | |
| Power on t | time | | 0.5 | 0.5 | 0.5 | 0.5 | 0.5 | S | |
| Response | frequency | 20Hz | | | | | | | |
| Interface | | TTL / RS232 / RS485 optional | | | | | | | |
| Communic | ation protocol | RION 68 protocol / MODBUS RTU protocol optional | | | | | | | |
| EMC | | According to EN61000 and GBT17626 | | | | | | | |
| MTBF | | ≥98000 hours/times | | | | | | | |
| Insulation | Resistance | | ≥100MΩ | | | | | | |
| Shockproc | f | | 100g@11ms / 3 Axial Direction (Half Sinusoid) | | | | | | |
| Anti-vibrati | on | 10grms / 10 ~ 1000Hz | | | | | | | |
| Protection | grade | IP67 | | | | | | | |
| Cables | | Standard conf | figuration: 1 | m length, w | ear-resistar | nt,oil-proof, | wide tempe | rature, | |
| | | shielded cable4*0.2mm2 | | | | | | | |
| Weight | | | ≤1 | 150g (includ | ing 1 meter | cable) | | | |

KEY WORDS

Resolution: Refers to the sensor in measuring range to detect and identify the smallest changed value.

MAXE: refers to the biggest error of the product within the range and at multiple angle points.

RMSE: refers to the root mean square difference between the measured value and the actual angle of the product within the range and for multiple times (more than 16 times).

Zero Temperature Drift Coefficient: the change rate of the indication value relative to normal temperature within the rated operating temperature range of the sensor at the zero degree.

Sensitivity Temperature Drift Coefficient: The percentage change rate with temperature of the full-scale indication relative to the full-scale indication at room temperature of the sensor in its rated operating temperature range.

▶ ELECTRONIC CHARACTERISTICS

| PARAMETERS | CONDITIONS | MIN | STAN | DARD | MAX | UNIT |
|---------------------|------------|-----|------|------|-----|------------|
| Power supply | Standard | 9 | 12 | 24 | 36 | V |
| Working current | No load | | 21 | 12 | | mA |
| Working temperature | | -40 | | | +85 | $^{\circ}$ |
| Store temperature | | -40 | | | +85 | $^{\circ}$ |












ORDERING INFORMATION



E.g : HCA716S-10-232-68 : Single axis / standard horizontal / $\pm 10^{\circ}$ measure range / RS232 signal output / RION68 protocol.

Note: Vertical measurement installation only for single axis X axis.


▶ MECHANICAL PARAMETERS

o Connector: 1m Direct Leading Cable (Can Be Customized)

o Protection level: IP67


o Shell material: aluminum alloy shield oxidation

o Installation: Four M4 screws



WORKING PRINCIPLE

Adopt imported core control unit and apply the principle of capacitive micro-pendulum. Using the principle of earth's gravity, when the tilting unit tilts, the earth's gravity will produce a gravitational component on the corresponding pendulum, and the corresponding electric capacity will change. By amplifying and filtering the electric capacity, the inclination is obtained after conversion.



 $U_{\text{R}},\,U_{\text{L}} \text{Respectively}$ is the pendulum left plate and the right plate corresponding to their respective voltage between theelectrodes, when the tilt sensor is tilted, $U_{\text{R}},\,U_{\text{L}}$ Will change according to certain rules, so $f(U_{\text{R}},\,U_{\text{L}},\,)$ On the inclination of α function:

$$\alpha$$
= (U_R, U_L,)

ELECTRICAL CONNECTION

| FU | BLACK | WHITE | GREEN | RED |
|-------|----------|------------|------------|--------------|
| NCT | GND | RS485(D+) | RS485(D-) | DC9~36V |
| COLOR | Power | RS232(RXD) | RS232(TXD) | Power supply |
| | negative | TTL(RXD) | TTL(TXD) | positive |















▶ DIMENSION



Shell size: L56×W46×H20.5mm Installation size: L48.5×W38.5×H6.5mm ounting screws: 4 M4 screws









0.50 mm




▶ PRODUCTION INSTALLATION NOTES

Please follow the correct way to install tilt sensor, incorrect installation can cause measurement errors, with particular attention to the "surface", "line"::


- 1)The Sensor mounting surface and the measured surface must be fixed closely, smoothly, stability,if mounting surface uneven likely to cause the sensor to measure the angle error.
- 2) The sensor axis and the measured axis must be parallel ,the two axes do not produce the angle as much as possible.







MEASURING DIRECTIONS

The installation must guarantee the product bottom is parallel to measured face, and reduce the influence of dynamic and acceleration to the sensor. This product can be installed horizontally or mounted vertically (vertical installation selection is only applicable to single axis), for installation please refer to the following scheme.





Horizontal installation





Earth

Horizontal-down installation






















Vertical-left installation





Vertical-right installation



Vertical installation

8 / 15











▶ 68 COMMUNICATION PROTOCOL

1. Data frame format: (8 data bits, 1 stop bit, No check, default rate is 9600)

| Identifier (1byte) | Date Length (1byte) | Address code (1byte) | Command Word (1byte) | Date domain | Check sum (1byte) |
|-----------------------|------------------------|----------------------------|-------------------------|-------------|----------------------|
| 68 | | | | | |

Data format: hexadecimal.

Identifier:Fixed68.

Data length: From data length to check sum (including check sum) length.

Address code: Accumulating module address, Default: 00.

Date domain will be changed according to the content and length of command word.

Check sum:Data length/Address code/Command word and data domain sum,No carry.

2. COMMAND word analysis

Attention to parameter setting: All settings required by the 68 command should be saved by sending the command 6804005357 to save the parameters.

| Comman d word | Meaning/Example | Description |
|------------------|--|---|
| 0X04 | Read X and Y angle commands simultaneously E.g: 68 04 00 04 08 | Data domain(0byte) No Data domain command |
| 0X84 | Sensor response /answer E.g: 68 0F 00 84 00 20 10 00 10 05 25 00 00 50 50 9D | Data domain(9byte) SA AA BB CC SD DD EE FF SG GG HH SA AA BB CC: 4 characters represent the X axis. 00 20 10 00 The four red bytes return the angle value for the X axis,is compact BCD code,High byte of the first byte 0 is Sign bit(0 positive,1 negative)020 is a three-digit integer value,10 00 is four Decimal value. Other axis data is the same. This angle analyze +20.100deg. 10 05 25 00: Four characters represent Y axis. 00 50 50:The internal temperature value of the three-character,analyze in the same way as the X-axis angle. Angle format is the same as X axis or Y axis for analyze. The angle in the left example is: X axis 20.10deg, Y axis -5.25deg, Temperature:+50.5°C |
| 0X05 | Setting relative/absolute zero: Can set the current angle to Zero degree for relative measurement, can also be set to absolute ex-factory zero, power off save. E.g: 68 05 00 05 00 0A | Data domain(1byte) 00 Absolute ZERO 01 Relative ZERO |
| 0X85 | Sensor response /answer command E.g:68 05 00 85 00 8A | Data domain (1byte) The number in the data domain indicates the result of the sensor response 00 Success FF Failure |









| 0X0B | Setting communication rate E.g:68 05 00 0B 03 13 Note: It will take effect immediately after setting (but not saved to FLASH) Sensor response /answer | Data domain(1byte) Baud rate:Factory default 9600 00 means 2400 |
|------|--|--|
| 0X8B | command E.g: 68 05 00 8B 00 90 | The number in the data domain indicates the result of the sensor response 00 means Success FF means Failure |
| 0X0C | Setting sensor output mode Response rule:Need upper computer send reading angle command, the sensor answer the corresponding angle. Automatic output Mode: The sensor automatically outputs X and Y angles when powered on, with the output frequency specified in the table on the right. (Power-off memory is supported.) E.g:68 05 00 0C 00 11 | Data domain(1byte) 00:Answer reply mode(Factory default) 01:5Hz Auto output mode 02:15Hz Auto output mode 03:25Hz Auto output mode 04:35Hz Auto output mode 05:50Hz Auto output mode Note: When the setting value is greater than 128, the output frequency is calculated as XX minus 128; for example, 81H corresponds to 1 Hz. When using the RS485 bus, automatic output is only supported when a single device is connected. |
| 0X8C | Sensor response /answer command E.g:68 05 00 8C 00 91 | Data domain (1byte) The number in the data domain indicates the result of the sensor response 00 Success FF Failure |
| 0X0F | Setting module address command The sensor default address is 00. 1.such as a plurality of sensor to be connected with a bus cable, e.g RS485.requires each sensor is set to a different address, in order to achieve control and response angle. 2.If successfully changed the new address, follow all of the commands and responding Packet address code has to switch to the new address code which already changed then to be effective, otherwise the sensor will not respond to commands. E.g:68 05 00 0F 01 15 Setting the address to 01. 68 05 FF 0F 00 13 Use the common address to reset address to 00. | Data domain(1byte) XX Module address Address from 00 to EF range Note: All products have a common address:FF, If forget the address what has been set during operation, can use FF address to operate the product can still normally respond. Note: It will take effect immediately after setting (but not saved to FLASH) |
| 0X8F | Sensor response /answer command E.g:68 05 00 8F 00 94 | Data domain (1byte) The number in the data domain indicates the result of the sensor response 00 Success FF Failure |









| 0X0D | Query relative/absolute ZERO Used to query the sensor current ZERO mode is relative ZERO or absolute ZERO E.g:68 04 00 0D 11 | Data domain(0byte) No Data domain command | | | | |
|------|--|---|--|--|--|--|
| 0X8D | Sensor response /answer command E.g:68 05 00 8D 00 92 | Data domain (1byte) The number in the data domain indicates the result of the sensor response 00 Absolute ZERO 01 Relative ZERO | | | | |
| 0X53 | Set save command E.g:68 04 00 53 57 | Data domain(0byte) No Data domain command | | | | |
| 0X53 | Sensor response /answer command E.g:68 05 00 D3 00 D8 | Data domain(1byte) The number in the data domain indicates the result of the sensor response 00 Success FF Failure | | | | |
| 0X1F | Read software version number | No data domain | | | | |
| 0X9F | Sensor response reply command E.g:68 14 00 9F 52 43 41 38 32 36 54 5F 56 32 31 30 34 30 38 41 A2 | Data domain(16byte) The data field is in string format As version number: HCA726T_V210408A | | | | |









PRODUCT MODBUS COMMUNICATION PROTOCOL

Attention, please read the following items carefully before use:

- 1. Due to the MODBUS protocol's requirement that the time between two data frames should be at least 3.5 bytes (e.g. at 9600 baud rate, this time is 3.5 x (1/9600) x 11=0.004s). But in order to leave enough margin, this sensor has increased this time to 10ms, so please leave at least 10ms of time interval between each data frame. Host sends command -10ms idle Slave replies command -10ms idle Host sends command
- 2. The MODBUS protocol specifies the relevant content of broadcast address -0, and this sensor can also accept broadcast address content, but will not respond to it. So the broadcast address 0 can be used for the following purposes, for reference only.
- 1) Set all the addresses of the tilt sensors of this model mounted on the bus to a certain address.
- 2) Set all tilt sensors of this model mounted on the bus to relative/absolute zero.
- 3) Test the sensor of this model on the entire bus, that is, if the host sends a 0 address inquiry angle command to the bus and the communication indicator light flashes, the communication is normal.
- 3. In order to improve the reliability of the system, the address command and absolute/relative command, as well as the baud rate, must be sent twice in a row to be effective. 'Sending twice in a row' refers to sending successfully twice (with a response from the slave each time), and the two question and answer sessions must be consecutive, meaning that the host cannot insert other data frames in between. Otherwise, this command will be locked until power is lost. The setup process is as follows: Send Set Address Command Wait for Successful Setting Command from Slave (No other commands allowed) Send Set Address Command Again Wait for Successful Setting Command from Slave Modify Successful
- 4. After power on, the address command, baud rate, and communication character format can only be set once. If you need to set them again, you need to power on again.
- 5. When normal communication accumulates to a certain number of times, the communication indicator light will flash once.

1.One Data frame format

RTU mode.

Communication parameters: baud rate 9600 bps.

Data frame: 1 start bit, 8-bit data, even parity check, 1 stop bit.

2.Read angle data

Modbus function code 03H, application example of read data command:

| Host query command: | | Slave response: | | | |
|-------------------------|-------|-------------------|-------|--------|--|
| Sensor address | 01H | Sensor address | 0 | 1H | |
| function code | 03H | function code | 0: | 3H | |
| Accessing the first | 00H | Data field length | 0 | 8H | |
| address of the register | 02H | | 5AH | | |
| Number of registers | 00H | | 60H | X-axis | |
| Number of registers | 04H | | 01H | data | |
| CRC | E5C9H | Data domain | 00H | | |
| | | | 47H | | |
| | | | 62H | Y-axis | |
| | | | 01H | data | |
| | | | 00H | | |
| | | CRC | C5B9H | | |









Note: The data fields of the slave reply frame are 5AH, 60H, 01H, 00H, 47H, 62H, 01H, 00H. The X-axis represents the first to fourth bytes of the data field, the Y-axis represents the fifth to eighth bytes of the data field, and the lower bytes come first. The representation method of angle is point based representation, where one point corresponds to 0.001° and 0.001 × (point offset) is the angle. If the measurement range is+-180°, the total number of points is 360000. So 0 corresponds to -180°, 360000 corresponds to+180°, and 180000 corresponds to 0°. Taking the above data frame as an example, the process of angle conversion is as follows:

- 1) Obtain the current angle point count, note that the low byte comes first, the X-axis is 0001605AH, and the Y-axis is 00016247H.
- 2) Convert to decimal, X-axis: 0001605AH \rightarrow 90202, Y-axis: 00016247H \rightarrow 90695.
- 3) Subtract the offset of 180000 (note: this value is a quantity related to the measurement range),

X-axis: 9002-180000=-89798, Y-axis: 90695-180000=-89305.

4) Obtain the final angle, X-axis: -89798 × 0.001=-89.798 °, Y-axis: -89305 × 0.001=-89.305 °.

3.Set the relative/absolute zero point of the sensor: (MODBUS function code 06H)

| Set relative/absolute zero command: | | | | Slave re | esponse: | | | | |
|--|----|-----------------------|-----|--|----------------------|---------------|--------------------------------|-----|-----|
| Sensor address | | 01H | | Sensor address | | ss | 01H | | |
| function code | | 06H | | func | tion code | • | | 06H | |
| Accessing the first | | 00H | | Dagia | Register address 10H | | | | |
| address of the register | | 10H | | Regis | | | 10H | | |
| If the character is | | 00 H | | If the character is non-zero, it is a relative zero point, and if it is zero, it is an absolute zero point | | 0011 | | | |
| non-zero, it is a relative zero point, and if it is zero, it is an absolute zero point | | FFH / 00 ative/Aba | | | | int, it is | FFH / 00H Relative/Absolute | | ute |
| CRC | C8 | 84FH/ 88 | 0FH | | CRC | | C84FH/ 880FH | | |
| Example of setting relative/absolute zero command application: | | | | | | | | | |
| Host sends 01H 06H | | 00H | 10H | 00H | FFH | C8H | 4FH | | |
| Reply from the machine | | 01H | 06H | 00H | 10H | 00H | FFH | C8H | 4FH |

Note: 0010 is the register address, which controls whether the sensor output is relative zero or absolute zero If it is non-zero (as in the above example, 00FFH is written), then the output is relative zero On the contrary, if it is zero (by changing the 5th and 6th bytes to 00H), it is an absolute zero The last two bytes are the CRC checksum.

4. Set sensor address:

| Set sensor addre | ess code command: | Slave response: | | |
|-------------------|-------------------|------------------|------|--|
| Sensor address | 01H | Sensor address | 01H | |
| function code | 06H | function code | 06H | |
| address | 00H | Pogistor address | 00H | |
| address | 11H | Register address | 11H | |
| New address | 00 H | New address for | 00 H | |
| for sensor | 04H | sensor | 04H | |
| CRC | D80C | CRC | D80C | |

The command must be sent twice in a row to be effective











| Example application of setting sensor address command: | | | | | | | | |
|--|------|------|------|------|------|-----|------|-----|
| Host sends | 01 H | 06 H | 00 H | 11 H | 00 H | 04H | D8H | 0CH |
| Reply from the machine | 01 H | 06 H | 00 H | 11 H | 00 H | 04H | D8 H | 0CH |

Note: 0011H is the register address, which controls the sensor address In the above example, the address of the sensor is changed to 0004H, and the last two bytes are the CRC checksum.

5. Set sensor baud rate: (Factory default is 9600bps)

| Set sensor baud | rate: | Slave response: | | |
|-------------------|--------|----------------------|--------|--|
| Sensor address | 01H | Sensor address | 01H | |
| function code | 06H | function code | 06H | |
| address | 00H | Register address | 00H | |
| address | 12H | Register address | 12H | |
| The baud rate | 00H | The baud rate of the | 00H | |
| of the sensor | XX | sensor | XX | |
| CRC | CRC LH | CRC | CRC LH | |

XX: A0H:4800 A1H:9600 A2H:19200 A3H:38400 A4H:115200

The command must be sent twice in a row to be effective

| Example application of setting sensor baud rate command: | | | | | | | | |
|--|------|------|------|------|------|-----|------|-----|
| Host sends | 01 H | 06 H | 00 H | 12 H | 00 H | A2H | A8H | 76H |
| Reply from the machine | 01 H | 06 H | 00 H | 12 H | 00 H | A2H | A8 H | 76H |

Note: 0012H is the register address, which controls the sensor baud rate In the above example, the baud rate of the sensor is set to 19200, and the last two bytes are the CRC checksum.

6. Set sensor communication character format:

| Set sensor communication character format: | | | Slave response: | | | | | | | |
|---|------|------|-------------------|------------------------|------|-------|-----|----|------|-----|
| Sensor address | 01H | | Sensor address | | | 01H | | | | |
| function code | 06H | | | function code | | ode | 06H | | | |
| address | 00H | | | Register address | | r | 00H | | | |
| | 09H | | | | | • | 09H | | | |
| Sensor changes communication character format | 00 H | | | New format for sensors | | t for | 00H | | | |
| | 01H | | | | | | 01H | | | |
| CRC | 9808 | | | | CRC | | 9 | | 9808 | |
| Example of setting sensor communication character format application: | | | | | | | | | | |
| Host sends | 01 H | 06 H | 00 | Н | 09 H | 00 F | H C | 1H | 98H | 08H |
| Reply from the machine | 01 H | 06 H | 00 | Н | 09 H | 00 H | H C | 1H | 98 H | 08H |

The above example is to set the byte format to: one start bit+8 data bits without parity+1 stop bit.

Effective after powering on again The factory default is a start bit+8 data bit parity+1 stop bit. Note: 0009 is the register address, which controls the communication character format of the sensor.

0000H: One start bit+8 data bit parity checks+1 stop bit.

0001 H: One start bit+8 data bits without checksum+1 stop bit.

7. Set sensor output mode: (factory default 0HZ)

| Set sensor output mode command: | | Slave response: | | | | |
|---------------------------------|-----|-----------------|-----|--|--|--|
| Sensor address | 01H | Sensor address | 01H | | | |









| function code | 06H | function code | 06H | | |
|----------------|--------|------------------|--------|--|--|
| address | 00H | Pagiator address | 00H | | |
| | 13H | Register address | 13H | | |
| Output mode of | 00H | Output mode of | 00H | | |
| sensor | XX | sensor | XX | | |
| CRC | CRC LH | CRC | CRC LH | | |

When the set value is greater than 128, the output frequency is XX-128; If 81H is 1Hz.







