





## Wiring description

| Pin | 4-pin socket                                                                                       |
|-----|----------------------------------------------------------------------------------------------------|
| 1   | U frequency converter phase                                                                        |
| 2   | V frequency converter phase                                                                        |
| 3   | W frequency converter phase                                                                        |
| 4   | Wring ground  |

## 【CAUTION】

Rotating mode: anticlockwise from the shaft extension end

## ATO SPINDLE MOTOR

| Power | Voltage | Current | Shaft | Frequency | Speed    | Cool  | Weight |
|-------|---------|---------|-------|-----------|----------|-------|--------|
| 3.7KW | 220V    | 10.0A   | ER20  | 400Hz     | 24000RPM | Water | 8.8KG  |